

Illustrated Parts List - IPL Update



Product Name(s)

530iPT5

Description of change

Motor assy 587 69 08-01 replaced by Motor kit 546 70 36-01 including Motor (529 65 38-01), Disc spring (597 67 01-01), Washer (503 23 00-35) and Screw (503 21 53-20) (see Reference 1 in page 2).

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
A SAW HEAD	4		MOTOR ASSY	587 69 08-01	Old motor
A SAW HEAD	30	546 70 36-01	MOTOR KIT		New motor. Will replace 587 69 08-01 after stock is finished.
A SAW HEAD	31	529 65 38-01	MOTOR		New motor for MOTOR KIT 546 70 36-01.
A SAW HEAD	23	See Remark	WASHER	577 27 15-01	Only for old motor 587 69 08-01 and CUTTING SYSTEM 529 53 71-01 without screw hole in the motor shaft (see Reference 2 in page 3).
A SAW HEAD	24	See Remark	CIRCLIP	735 31 12-00	Only for old motor 587 69 08-01 and CUTTING SYSTEM 529 53 71-01 without screw hole in the motor shaft (see Reference 2 in page 3).
A SAW HEAD	29	See Remark	CUTTING SYSTEM	529 53 71-01	New CUTTING SYSTEM includes the new motor (shaft with screw hole, see Reference 2 in page 3).
A SAW HEAD	32	597 67 01-01	DISC SPRING		see Reference 2 in page 3.
A SAW HEAD	33	503 23 00-35	WASHER		see Reference 2 in page 3.
A SAW HEAD	34	503 21 53-20	SCREW		see Reference 2 in page 3.